


CITY OF STAMFORD

MAYOR
MICHAEL A. PAVIA
ACTING DIRECTOR OF OPERATIONS
ERNIE ORGERA
Email: eorgera@ci.stamford.ct.us



CITY ENGINEER
LOUIS CASOLO, JR., P.E.
Email: lcasolo@ci.stamford.ct.us
DEPUTY CITY ENGINEER/
TRANSPORTATION DIRECTOR
EDWARD GENTILE, JR., P.E.
Email: egentile@ci.stamford.ct.us

OFFICE OF OPERATIONS ENGINEERING BUREAU

Tel: (203) 977-4180/Fax: (203) 977-4137
Government Center, 888 Washington Blvd., Stamford, CT 06901

December 15, 2009

Mitchell Kaufman
Chair of Scofieldtown Task Force

**RE: Supplemental Site Investigation
Scofieldtown Park Area**

Dear Mr. Kaufman:

Attached please find a copy a "Status" report by TRC. To date TRC has completed the following tasks:

- Task 1 - GPR Survey
- Task 2 – Soil Sampling
- Task 3 – Surface Water Sampling
- Task 4 – Monitoring Well Installation (13 completed)
- Task 5 – Monitoring well sampling (11 completed, 2 GW analyses pending).

An executive summary:

- Following GPR Survey, no clustering of buried drums or UST's detected.
- Soil Sampling, See Table 1/Figure 3 for results (**Bold Faced** or Shaded represent exceedances of CT remediation standards).
- Surface Water Sampling, See Table 2/Figure 3 for results (**Bold Faced** represents Benzene exceedance of CT remediation standards at SW-2 (unnamed brook).
- Monitoring Well Analyses, See table 3/Figure 4 for results (**Bold Faced** or Shaded represent exceedances of CT remediation standards. 4 out of 11 wells have exceedances.

No pesticides were detected in the monitoring wells located in Scofieldtown Park or from the well located at Scofieldtown school. Pesticides were detected in the monitoring wells located at the cul-de-sac at Very Merry Rd. and Alma Rock Road.

All figures attached with the status report will be made available in a larger scale for presentation at tomorrow night's meeting.

TRC will also review the available data regarding the previous investigation undertaken by the USEPA and others at the Park to provide an approach for future actions at the Park and former landfill area. I will discuss appropriate actions as soon as this information is received.

If you have any questions regarding this information please do not hesitate to call me at 203-977-5796.

Regards,

A handwritten signature in black ink, appearing to read 'L. Casolo'.

Lou Casolo, P.E.
City Engineer